

# Oil Field Environmental Incident Summary

**Incident:** 20131125102900      **Date/Time of Notice:** 11/25/2013 10:17

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** BERING 5200 12-29H

**Field Name:** CAMP

**Well File #:** 20400

**Date Incident:** 11/23/2013      **Time Incident:** 0600

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 100

**Sec:** 29

**Qtr:**

**Location Description:**

**Submitted By:** Todd Hanson

**Received By:**

**Contact Person:** Todd Hanson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Miles

**Distance Nearest Water Well:** 3 Miles

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Unknown

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	100	barrels	80	barrels	80	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/15/2016

**Clean Up Concluded:** 12/15/2013

**Risk Evaluation:**

minimal

**Areal Extent:**

**Potential Environmental Impacts:**

minimal

**Action Taken or Planned:**

Spill was contained in dikes, crews are working on the clean up.

**Wastes Disposal Location:** recovered oil is back into production tanks, other waste will go to solid waste disposal

**Agencies Involved:**

**Updates**

---

**Date:** 12/2/2013    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Wording in report indicates that the spill remained on location, but then it also states that the spill didn't remain on location. Followup necessary to clarify reporting.

---

**Date:** 12/5/2013    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

9:42, on location. Ice and snow on site. Oasis personnel indicated overflow occurred in the western-most tanks of the battery (LACT tanks). Site has multiple sets of berms. Visible stain on scoria within tank battery. No visible staining on metal berm around tanks, or berm ~20' to west on edge of site.